


Rear View Front View XXII Missing foot Add-ons Loose/broken/delaminated Missing Previous repair Spindles not original to desk Replaced piece Inscriptions Damage/wear/hole


Right Side







Top













Bottom


Bottom





Drawer Front, Outer Surface


Rear Surface of Drawer Front















Inside Surface of Left Drawer Side


Inside Surface of Right Drawer Side





Rear Surface of Drawer Back

Front Surface of Drawer Back












Upper Surface of Drawer Bottom

Lower Surface of Drawer Bottom



Outside Surface, Right Drawer Side

Outside Surface, Left Drawer Side

